



Medical Devices Bureau, Ministry of Health Malaysia
Level 4&5, Block E6, Parcel E, Precint 1,
Federal Government Administration Centre,
62590 Putrajaya
Tel: 03-8883 2248/2249/2264
Fax: 03-8888 6184

Medical Device / Equipment RECALL

Date Issued : 7 April 2008

Ref:MDB/R/2008/001

IMMEDIATE ACTION	√
ACTION	
UPDATE	
INFORMATION REQUEST	

PRODUCT	Implantable Cardioverter Defibrillator (ICD) lead. Sprint Fidelis manufactured by Medtronic, Model numbers: 6930, 6931, 6948 and 6949.
CLASS	Not Mentioned By The Manufacturer
USE	Implantable Defibrillator
SOURCE OF MEDICAL DEVICE RECALL / ALERT	MHRA website, date issued: 19 th October 2007
RECALLING FIRM	Medtronic International Ltd.
REASON FOR RECALL	<p>ICD lead recall due to risk of inappropriate patient shocks, loss of defibrillation therapy and/or loss of pacing output, caused by fracture of the lead conductor.</p> <p>The MHRA has received 23 reports of lead conductor fracture for the above models (6930, 6931, 6948 and 6949), among approximately 6900 leads distributed in the United Kingdom.</p> <p>This includes one ongoing investigation of a fatality which may have been a consequence of lead fracture. Fractures typically occur at two main sites on the lead: one at the ring electrode affecting the anode conductor; the second near the anchoring sleeve tiedown affecting the cathode conductor and occasionally the high voltage conductor.</p> <p>In the UK, incident reports have included:</p>

	<ul style="list-style-type: none"> • delivering a number of inappropriate shocks • oversensing caused by noise on the lead • an increase in the pace/sense or shock lead impedance. <p>Medtronic has informed the MHRA that it is suspending distribution of all models of the Sprint Fidelis lead and is recalling all un-implanted stock.</p> <p>The company communicated this to all its customers in its ‘Urgent Medical Device Information’ issued on 15 October 2007.</p> <p>This provides important programming advice to help increase the chance of early detection of lead fracture, and reduce the risk of inappropriate therapy.</p> <p>However, it is important to note that all ICD leads, not only Medtronic’s Sprint Fidelis models, are associated with a small risk of conductor fracture once implanted, and the steps identified in Medtronic’s notice would not necessarily identify fractures in all cases.</p>
<p>SCENARIO IN MALAYSIA</p>	<p>No details available at this moment.</p>
<p>ACTION</p>	<p>If the device is available, clinician should:-</p> <p>Follow up all patients as soon as practicable, ideally within eight weeks.</p> <p>– Review the following parameters which can indicate lead fracture:</p> <ul style="list-style-type: none"> <input type="checkbox"/> number of inappropriate shocks <input type="checkbox"/> oversensing and noise on the RV Lead <input type="checkbox"/> an increase in the lead impedance <input type="checkbox"/> an increase in the noise sensing on the noise integrity counter. <p>– Consider provocative testing (eg shoulder/arm movements, and deep respiration by the patient), which may help confirm a suspected lead fracture, although this diagnostic method should not be relied upon alone.</p> <p>– Programme the patient’s ICD where appropriate to the following parameters as outlined in Medtronic’s ‘Urgent Medical Device Information’:</p> <p>To reduce inappropriate shocks due to oversensing:</p> <ul style="list-style-type: none"> • Program VF detection for initial number of intervals to detect (NID) to nominal settings (18/24) or longer at clinical discretion and redetect NID to nominal settings of

	<p>(12/16).</p> <ul style="list-style-type: none"> • Where clinically appropriate increase the number of intervals to detect in the VT zones. <p>To increase the chance of detection of lead fracture</p> <ul style="list-style-type: none"> • Turn ON patient alert pacing, RV and SVC defibrillation impedance. • To optimise effectiveness of the lead impedance alert: <ul style="list-style-type: none"> – Review V pacing lead performance trend to determine typical chronic impedance value for the patient (typical values for Fidelis leads should be 350-1,000 ohms). – Programme lead impedance alert threshold for RV pacing to 1,000 ohms if the typical chronic impedance for the patient is ≤ 700 ohms, or – Programme lead impedance alert threshold for RV pacing to 1,500 ohms if the typical chronic impedance for the patient is > 700 ohms. – Programme lead impedance alert threshold for RV defibrillation and SVC defibrillation to 100 ohms
<p>RECOMMENDATION</p>	<p>To all users and healthcare providers having the abovementioned device used in their premises.</p> <p>Users of the abovementioned device should contact the distributors of this device (if available) and inform the Medical Devices Bureau, Ministry of Health providing the following information:-</p> <ol style="list-style-type: none"> a. Name of healthcare centre/hospital/clinic b. Contact person and contact number c. Numbers of units available
<p>CONTACT/ENQUIRIES</p>	<p>Medtronic International Ltd.-Malaysia Branch F-39-7 CREST, 3 Two Square No. 2, Jalan 19/1 46300 Petaling Jaya Selangor Darul Ehsan</p> <p>Tel:- 03-79534800</p>
<p>REFERENCES</p>	<p>https://www.mhra.gov.uk/Publications/Safetywarnings/MedicalDeviceAlerts/CON2032785</p>